

# 99V340000: ROTOR REPLACEMENT

1993 Jeep Cherokee

NHTSA RECALL BULLETIN

## VEHICLE DESCRIPTION

Model(s) :	1992 Jeep Cherokee
	1993 Jeep Cherokee
	1993 Jeep Grand Wagoneer
	1994 Jeep Cherokee
	1994 Jeep Grand Cherokee
	1995 Jeep Cherokee
	1995 Jeep Grand Cherokee
Campaign No:	99V340000
Mfg. Campaign No:	747
Number of Affected Vehicles:	334047

Passenger and multi-purpose vehicles originally sold in (or are currently registered in) the states of Connecticut, Illinois, Indiana, Maine, Maryland, Massachusetts, Michigan, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, or Wisconsin, and the District Of Columbia.

## DESCRIPTION OF DEFECT

The front disc brake rotors can experience severe corrosion if operated for an extensive period in the "salt belt." if the rotors are not replaced, the corrosion can eventually compromise the structural integrity of the stamped steel center hub section of the rotor.

## CONSEQUENCE OF DEFECT

The reduced strength can allow the cast iron wear surface to separate from the hub, reducing the brake effectiveness of the vehicle.

## CORRECTIVE ACTION

Dealers will replace these rotors with rotors that are coated with a corrosion protection.

## OWNER NOTIFICATION

Owner notification began December 20, 1999. Owners who take their vehicles to an authorized dealer on an agreed upon service date and do not receive the free remedy within a reasonable time should contact daimlerchrysler at 1-800-992-1997. Also contact the National Highway Traffic Safety Administration's Auto Safety Hotline at 1-888-dash-2-dot (1-888-327-4236).

## ADDITIONAL INFORMATION

The National Highway Traffic Safety Administration operates Monday through Friday from 8:00 AM to 4:00 PM, Eastern Time. For more information call (800) 424-9393 or (202) 366-0123. For the hearing impaired, call (800) 424-9153.

