

# HEATER SYSTEM TROUBLE SHOOTING

1988 Jeep Cherokee

1989 HEATER SYSTEMS  
Eagle Trouble Shooting

CONDITION & POSSIBLE CAUSE

Little or No Air From Heater Floor Outlets.

- \* Misadjusted heater air door cable.
- \* Obstructed heater housing or ducts.
- \* Clogged heater core fins.
- \* Leaking air duct seals.

Little or No Air From Defroster Outlets.

- \* Defroster duct misaligned.
- \* Defroster cable incorrectly adjusted
- \* Leaking air duct seals.
- \* Defroster duct damaged.

Heat Output When Controls Are Off.

- \* Outside air cable misadjusted
- \* Outside Air door binding in housing.

Not Enough Heat With Controls Fully On.

- \* Low coolant or plugged heater core.
- \* Incorrect thermostat.
- \* Incorrect adjustment of cables.
- \* Heater System Air Leaks.
- \* Blend air door not in proper position.

Blower Will Not Run.

- \* Blown fuse.
- \* Loose connections or poor ground.
- \* Faulty switch, motor or resistor.

Blower Runs But Does Not Circulate Air.

- \* Intake blocked..
- \* Fan not attached to motor shaft.